

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CA384
East
1/2-1
0.619 mi.
3268 ft.

APT BLDG
2935 OCEAN PARKWAY
BROOKLYN, NY

Site 3 of 3 in cluster CA

NY Spills **S118459812**
N/A

Relative:
Higher

Actual:
7 ft.

SPILLS:

Name: APT BLDG
Address: 2935 OCEAN PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1508686 / 2016-03-28
Facility ID: 1508686
Facility Type: ER
DER Facility ID: 255311
Site ID: 517258
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2015-11-20
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2015-11-20
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2015-11-23
Spill Record Last Update: 2016-03-28
Spiller Name: Michael Olbach
Spiller Company: 2935 OP LLC
Spiller Address: 111 oriental blvd
Spiller Company: 999
Contact Name: MICHAEL OLBACH
DEC Memo: "pbs- 2-601442 2935 OP LLC 111 Oriental Blvd Brooklyn, NY 11235
Michael Olbach 718-615-1157 11/21/15- DEC Piper responded to site in morning of 11/21/15. Met with Eric S of Approved and Chris Q from all boro. Drums from #2 F/o spill were on site. Evidence of #6 f/o cont was present in excavations. Tank in basement was new. IT is not registered. The old tank floated and rolled during Hurricane Sandy. Letter needs to be sent out. 3/24/16- DEC Piper received closure documentation. Based on work to date, this spill is closed. See report in dec docs if warranted. "

Remarks: "While cleaning overfill of #2 Fuel oil,, pools of #6 oil were observed coming back into excavation."

All Materials:

Site ID: 517258
Operable Unit ID: 1266344
Operable Unit: 01
Material ID: 2270222
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material FA:
Quantity:
Units:
Recovered:
Oxygenate:

Petroleum
Not reported
G
Not reported
Not reported